Adhesives



APM Unocol 38

	Description
System:	UV/anaerobic curing adhesive
Adhesive type	: modified acrylate
Colour:	transparent, slightly yellowish
Viscosity:	20 Pa.s
Solid bodies:	100% / solvent-free
Curing:	UV light / anaerobic or thermal
Temp. range:	-55°C to +125°C, sealed to +150°C

Application / specifications		
APM number:	102833	
Application:	Optics / Instruments	
Adhesion on:	glass / metal / plastics	
Biocompatibility:	not certified	
Directive 2011/65/EC:	complies with RoHS Directive	
EC No. 1907/2006:	complies REACH requirements	

Unocol 38 is a flexible acrylate adhesive. The adhesive is curable with UV light, anaerobic or oven. Typical applications for Unocol 38 include optics for low-tension plastic, metal or glass bonds. It is also used as an adhesive for lenses and prisms. A thin glue line of 0.15 mm is typical. It can be varied from 0.05 to 1 mm due to its high viscosity depending on the dimensions of the parts to be bonded, the temperature range and the difference in thermal expansion. Unocol 38 is often used to adhere plastic or glass displays and as an adhesive for electronic devices or sensors. The advantage of Unocol 38 is the long shelf life of the liquid adhesive at room temperature with the possibility of rapid curing under UV light and anaerobic or thermal post-curing in shadow areas.

Properties of fluid adhesive		
Colour:	transparent, yellowish	
Characterisation:	modified acrylate	
Viscosity (25°C):	20 Pa.s	
Density (25°C):	1.06 g/cm3	
Refractive index (25°C):	<u>1.48</u>	

Surface pretreatment / cleaning

The surfaces to be bonded must be dry and free from dust, oil, separating agents and other impurities. The selected type of surface pretreatment is dependent on the requirements profile (cleanliness, strength, age resistance). Above all, mechanical pretreatment, e.g. grinding or sand-blasting, achieves an improvement in adhesion for metals and in many cases for nonferrous surfaces as well. To clean mineral glass surfaces the best method is using the aqueous ultrasound cleaning method at raised temperature. Clean metallic surfaces also with aqueous cleaners or clean organic solvents.

Low pressure plasma cleaning has advantages for many materials and in particular plastics. Surface Treatment using oxygen or argon plasma has both proven higher adhesion of the adhesive. Plasma treatment dries the surface and improves wettability. This achieves good adhesion of the adhesive. The surface of plastics is also chemically modified. The adhesive will stick to the modified surface of the plastic.

Primers are no replacement for surface pretreatment. Adhesion and ageing resistance can also be improved by using primers. Primers are containing organic solvents which has also cleaning effect.



Page 2/4

The adhesive can be completely cured within a few seconds by exposure to UV light at a wavelength of 365 nm. In places where light fails to reach the adhesive, the adhesive can be post-cured using anaerobic or thermal methods.

Curing the adhesive		
Room temperature 50 mW/cm2	30 seconds	
Room temperature 500 mW/cm2	5 seconds	
Anaerobic curing with Activator	24 hours	
Heating Oven at 120°C	30 minutes	

After the adhesive is cured, the parts can be further processed. However, the bond only achieves optimum strength and resistance after a few days.

Properties of cured adhesive		
Colour:	transparent, yellowish	
Shore D (25°C):	60	
Thermal conductivity:	1.6 W/mK	
Therm. expansion (0-40 °C)	$\alpha = 120 \times 10^{-6}/K$	
(-40-0°C)	60 x 10 ⁻⁶ /K	
(40-85°C)	152 x 10⁻ ⁶ /K	
Softening temperature Tg:	40 to 50 °C	
Tensile strength (25°C):	25 N/mm2	
Elongation at rupture (25°C):	290 %	
Modulus of elasticity (25°C):	280 N/mm2	
Dielectric strength:	25.0 kV/mm	
Dielectric constant 25°C:	5.2 at 1.0 KC	

Applying the adhesive

The ideal processing temperature is between 20°C and 28°C. Viscosity falls at high temperature. It is not necessary to store the adhesive in the refrigerator after opening the container. Normally, the adhesive can be applied from the cartridge using a dosing device. The adhesive can also be applied with a steel needle or a brush. Optimum strength can be achieved with adhesive thicknesses of 0.05 to 0.15 mm. Optimum resistance is dependent on the temperature range and the expansion coefficients of single parts. A uniform adhesive thickness can be ensured by a specific bond geometry or by inserting spacers, e.g. glass fibres or plastic beads.

Cleaning the adhesive

Residue from non-cured adhesive on the substrates and processing equipment can be removed or cleaned using a solvent such as Isopropanol (IPA) or Acetone. Organic solvents may lead to component destruction or produce stress cracking in plastics. For this reason, avoid use of aggressive solvents such as Acetone, Ketones and Ethers if possible. Comply with the official safety regulations when handling combustible solvents.

Cured adhesive can only be removed using mechanically method. The adhesive becomes very soft at temperatures over 125 °C.

Technical data sheet

Adhesives



Page 3/4

Temperature stability

The typical application temperature range is from -55 °C to +125°C. Depending on the application, the adhesive can also be used below -55 °C. The adhesive becomes very hard at these temperatures and may result in cracks in the substrate or signs of the adhesive detaching from the substrate.

At temperatures of +125°C the adhesive becomes very soft, which may be an advantage depending on the load since the adhesive can compensate for a variety of thermal expansion scenarios without becoming destroyed. After cooling down to room temperature, the adhesive re-assumes its usual properties. Thermal destruction of the adhesive only occurs at temperatures over 175 °C.

Tensile shear strength / material

Tensile shear strength according to ASTM-D 1002 shows the excellent adhesion of the adhesive on various substrates:

Tensile shear strength at 23°C:		
Anodised aluminium (30 min/120°C)	10.6 N/mm ²	
Stainless steel (30 min/120°C)	13.1 N/mm ²	
Anodised aluminium with activator	10.0 N/mm ²	
Stainless steel with activator	15.2 N/mm ²	
Stainless steel on glass	16.5 N/mm ²	
Anodised aluminium on glass	10.2N/mm ²	
Polycarbonate on glass	8.2 N/mm ²	
ABS on glass	7.9 N/mm ²	
PVC on glass	8.8 N/mm ²	
Plexiglas (acrylate, perspex) on glass	6.6 N/mm ²	
GFK (epoxy) on glass	13.0 N/mm ²	

Ageing resistance of adhesive bonds

The typical application temperature range of Unocol 38 is from -55°C to +125°C. Adhesive bonds are very age resistant within this temperature range. The cured adhesive has excellent temperature stability and solvent resistance.

Tensile shear strength after ageing		
Stainless steel on glass at 25°C	16.5 N/mm ²	
Post-cured after 1 hour at 120°C	20.6 N/mm ²	
Thermal cabinet 14 days at +120°C	16.5 N/mm ²	
Thermal cabinet 14 days at +150 °C	11.3 N/mm ²	
Thermal cabinet 21 days at +120°C	15.0 N/mm ²	
Thermal cabinet 21 days at +150 °C	10.7 N/mm ²	
50°C / 90 % rel. hum. after 14 days	9.4 N/mm ²	
50°C / 90 % rel. hum. after 21 days	6.5 N/mm ²	
Boiling water after 2 h at 100°C	17.0 N/mm ²	
Stored in water 50°C after 7 days	15.3 N/mm ²	
Hydraulic oil 23 °C after 21 days	17.5 N/mm ²	
Isopropanol at 23°C and 24 h	16.5 N/mm ²	

Safety instructions

Avoid contact with skin and eyes. When applying the adhesive, always wear gloves and safety goggles. If adhesive comes into contact with the skin, do not use solvents to remove. Instead wash the affected area (hands) with warm water and soap and then dry. Liquid adhesive irritates on contact with the eyes and may lead to permanent eye damage. Before use, please observe the instructions in the safety data sheet.

Technical data sheet

Adhesives



Page 4 / 4

Storage

The adhesive has the best shelf life at temperatures between 8°C and 25°C. The adhesive shelf life in its unopened original packaging is at least 12 months under these conditions. Higher temperatures shorten the standard shelf life. Lower temperatures cause a temporary higher viscosity.

Compliance

Unocol 38 and all its constituents comply with the requirements of the RoHS Directive and REACH regulations. Always comply with the safety data sheet when handling the adhesive.

Procurement

The light-sensitive adhesive is available in black or amber-coloured standard cartridges of 5 / 10 / 30 or 55 cc. Unocol 38 can also be supplied to customer requirements filled in containers.

Disposal

The liquid components of the adhesive must be disposed of as hazardous waste in the same way as synthetic resin or paint components. Cured adhesive is disposed of as hazardous waste in the same way as thermosetting plastics depending on local legal requirements or as domestic waste.

The specifications in this data sheet are based on meticulous tests and our previous experience in everyday practice. They are non-binding instructions, in the same way as our application advisories are also non-binding, whether verbal, in writing or by trials since we cannot accept any liability due to the wide variety of possible influences during processing and application. APM Technica AG disclaims all other explicit or implicit warranties, conditions and terms, be they of real or legal nature, including those which refer to usual market quality, their suitability for a particular use, satisfactory quality or observance of third-party trademarks. APM Technica excludes all liability to the extent permitted by law - whether arising from contract, quasi contract or tort (including negligence) - for direct, indirect and consequential damages, punitive damages awarded by court, loss of business of all kinds, loss of information or data or any other financial losses which may result from the sale, installation, maintenance, use, performance, failure or interruption of operation of the product or in connection therewith, even if we were informed of the possibility of occurrence of such damages. Data and other specifications concerning the nature and suitability of our products are non-binding general conditions and specifically represent no guarantee of certain characteristics. We advise you to perform your own adequate tests to determine the suitability of our products for your specific application. The user is himself responsible for defining the suitability of production methods mentioned in the technical data sheet for his purposes and for taking precautionary measures which are suitable to protect assets and persons from any danger which may occur during the handling and usage of these products. In all other respects our General Terms and Conditions of Business shall apply.